


•  
•  
•

## 2 Modeling of DC machine

- 2.1 Theorem of operation
- Maximum torque is produced when two fluxes are in quadrature.



**Figure 2.1** Schematic representation of a dc machine

•  
•  
•

## 2.2 Induced EMF

- From Faraday's law, the induced emf is

$$e = Z \frac{d\phi_f}{dt} = Z \frac{\phi_f}{t}$$

where  $t$  is the time taken by the conductors to cut  $\phi_f$  flux lines. Therefore,

$$t = \frac{1}{2 \times \text{frequency}} = \frac{1}{2\left(\frac{P}{2}\right)\left(\frac{n_r}{60}\right)}$$

- Thus, (P: poles; Z: armature conductors;  $\phi_f$ : a flux per pole;  $n_r$ : rotation speed)

$$e = \frac{Z\phi_f P n_r}{60}$$

- 
- 
- 
- If the armature conductors are divided into 'a' parallel paths, then

$$e = \frac{Z\phi_f P n_r}{60}$$

wave winding:  $a = 2$ ; lap winding:  $a = P$ .

- The usual expression

$$e = K\phi_f\omega_m$$

where  $\omega_m = 2\pi n_r / 60$  rad/sec and  $K = (P/a)Z(1/2\pi)$

- If the field flux is constant, then emf is

$$e = K_b\omega_m$$

•  
•  
•

## 2.3 Equivalent circuit and electromagnetic torque

- The terminal relationship is


$$v = e + R_a i_a + L_a \frac{di_a}{dt}$$

- In steady state, the armature current is constant and hence

$$v = e + R_a i_a$$

- The power balance

$$vi_a = ei_a + R_a i_a^2$$



**Figure 2.2** Equivalent circuit of a dc motor armature

- 
- 
- 

- The power of mechanical form,  $P_a$  called the air gap power, is expressed in term of the electromagnetic torque and speed as

$$P_a = \omega_m T_e = e i_a$$

- Hence,

$$T_e = \frac{e i_a}{\omega_m} = \frac{K_b \omega_m i_a}{\omega_m} = K_b i_a$$

•  
•  
•

## 2.4 Electromechanical modeling

- The acceleration torque,  $T_a$ , drives the load and is given by

$$J \frac{d\omega_m}{dt} + B_1 \omega_m = T_e - T_1 = T_a$$

where  $J$ : a moment of inertia ( $\text{kg}\cdot\text{m}^2/\text{sec}^2$ )

$B_1$ : a viscous friction coefficient  $\text{N}\cdot\text{m}/(\text{rad}/\text{sec})$

$T_1$ : the load torque



•  
•  
•

## 2.5 State-space modeling

- The dynamic equations in state-space form

$$\begin{bmatrix} p i_a \\ p \omega_m \end{bmatrix} = \begin{bmatrix} -\frac{R_a}{L_a} & -\frac{K_b}{L_a} \\ \frac{K_b}{J} & -\frac{B_1}{j} \end{bmatrix} \begin{bmatrix} i_a \\ \omega_m \end{bmatrix} + \begin{bmatrix} \frac{1}{L_a} & 0 \\ 0 & -\frac{1}{J} \end{bmatrix} \begin{bmatrix} V \\ T_1 \end{bmatrix}$$

- The roots of the system are

$$\lambda_1, \lambda_2 = \frac{-\left(\frac{R_a}{L_a} + \frac{B_1}{J}\right) \pm \sqrt{\left(\frac{R_a}{L_a} + \frac{B_1}{J}\right)^2 - 4\left(\frac{R_a B_1}{J L_a} + \frac{K_b^2}{J L_a}\right)}}{2}$$

- 
- 
- 

## 2.6 Block diagrams and transfer functions

- From (2.13) and (2.19), we get

$$I_a(s) = \frac{V(s) - K_b \omega_m(s)}{R_a + sL_a}$$

$$\omega_m = \frac{K_b I_a(s) - T_l(s)}{(B_l + sJ)}$$


- The transfer functions

$$G_{\omega V}(s) = \frac{\omega_m(s)}{V(s)} = \frac{K_b}{s^2(JL_a) + s(B_l L_a + JR_a) + (B_l R_a + K_b^2)}$$

$$G_{\omega l}(s) = \frac{\omega_m(s)}{T_s(s)} = \frac{-(R_a + sL_a)}{s^2(JL_a) + s(B_l L_a + JR_a) + (B_l R_a + K_b^2)}$$

- The speed response due to the simultaneous voltage input and load torque disturbance is

$$\omega_m(s) = G_{\omega V}(s)V(s) + G_{\omega I}(s)T_1(s)$$




**Figure 2.3** Block diagram of the dc motor

- 
- 
- 


## 2.7 Field excitation

- Separately excited dc machine




**Figure 2.4** Separately-excited dc machine

- 
- 
- 
- Shunt-excited dc machine




**Figure 2.5** dc shunt machine

- Series-excited dc machine




**Figure 2.7** dc series machine

- DC compound machine



**Figure 2.9** DC compound machine

- Permanent-magnet dc machine



**Figure 2.10** Cutaway view of a conventional permanent-magnet dc motor assembly



•  
•  
•

## 2.8 Measurement of motor constants

- Armature resistance:

It is measured between the armature terminals by applying a dc voltage. (need to subtract the brush and contact resistance)

- Armature inductance:

By the test schematic shown in Figure 2.11, the inductance is

$$L_a = \frac{\sqrt{\frac{V_a^2}{I_a^2} - R_a^2}}{2\pi f_s}$$


$f_s$ : the frequency

$R_a$ : the armature ac resistance

- 
- 
- 

- EMF constant

Specified field voltage is applied and kept constant, and the shaft is rotated by another dc motor, and then the armature is connected a voltmeter.



**Figure 2.11** Measurement of armature inductance